

# **Usage Policy**

## Germanium (Ge) Target

1. Please take permission from System owner or Faculty in-charge before loading the target in the sputter system (ATC 2200).
2. In case the target is not loaded, please store the target in evacuated desiccators and place it near the sputter system.
3. Keep the target away from acids, alkalis, oxidizing elements and halogens.
4. Please use all the protective gears including face mask, safety glass and gloves while loading and unloading the target.

Thanks

Sachin Dev