

## **Usage Policy**

AR-300-76

### Process Guidelines

- Substrates coated with resist are exposed to the effect of the remover by immersion (puddle or dip).
- To reduce the dissolution time for tempered layers, removers AR 300-76 may be heated to up to 80 °C, or mega sound may be helpful in this case.
- It is recommended to rinse off the remover with DI water, clean remover or with a suitable thinner.
- A stripping of very hard-baked layers (> 220 °C) with remover is hardly possible any more. In this case, oxidizing acids or oxygen plasma may be used for stripping.