

Usage Policy

Tin-Germanium (Sn-Ge) Target

Targets:

- A) Ge(0.9)-Sn(0.1)
- B) Ge(0.96)-Sn(0.04)

1. Please take permission from Faculty in-charge and Student in-charge before loading the target in the sputter system ATC 2200/Orion.
2. In case the target is not loaded, please store the target in evacuated desiccators and place it near the sputter system.
3. Keep the target away from acids, alkalis, oxidizing elements and halogens.
4. Please use all the protective gears including face mask, safety glass and gloves while loading and unloading the target.
5. Please notify Student in-charge while loading and unloading the target. Presence of Student in-charge is desirable during target loading and unloading process .

Thanks

Sachin Dev