

Usage Policy for ZEP 520 A ebl
resist, ZED N 50 Developer, ZEP-A
Thinner, ZMD –D Rinse

Precautions:

Precautions for safe handling-

- Avoid contact with skin and eyes.
- Avoid formation of dust and aerosols.
- Provide appropriate exhaust ventilation at places where dust is formed.

Conditions for safe storage, including any incompatibilities-

- Store in cool place.
- Keep container tightly closed in a dry and well-ventilated Place

Material allowed in following tools: Spin coater , Hot plate , wet station and Raith. Metallization tools, plasma asher and lift off and etch process tools.

waste Disposal:

used developer and rinse should store in separate bottles.